

Excavators



1. All workers to wear **High Visibility** clothes and P.P.E.
2. All operators to prepare **Machine Check Sheets** prior to operating equipment.
3. Regulate **Scene Safe** before beginning work activities.
4. Maintain a **Clear Visual Path** around working area and workers.
5. Maintain **Line of Site** between operators and workers as well as pedestrians.
6. Operators to maintain **3 Point Contact** when entering and exiting excavators.
7. Use universal **Hand Signals** for contact and only approach Driver Side to avoid blind spots.
8. Identify **Danger Zone** areas and have them cornered off with safety apparatus.
9. **Cell phones** radios and devices are not to be used to during working time.
10. Never work under load.

1	6
2	7
3	8
4	9
5	10

Huddle Conducted By:

Superintendent/Foreman

Site Safety Representative